


RF Coax Connectors

Tools


Crimping Tools

Crimping tools are used for assembling coaxial connectors on coaxial cables. They can be applied particularly economically for small batch sizes.

The crimping dies are a fixed part of the crimping tools. Each tool is equipped with 2 or 3 different profiles. A total of 6 wioths across flats are possible with 2 tools, whose hand lengths are adapted to the dimensions of the hexagon profiles. The tools can be distinguished at a glance by different colored hancles.




Item	Width Across Flats of the Profile			Dim.	Color of	Part No.
	1	2	3	L	handles	Part No.
Orimping Tool	2.8 0.11	3.2 0.13	3.6 0.14	214.0 8.43	Green	1393524-4
Orimping Tool	2.8 0.11	5.4 0.21	4.5 0.18	260.0 10.24	Yellow	1393524-5



IDC Tool


For assembling IDC coaxial connectors Series 1.6/5.6 mS on coaxial cables.



Part No. 2-1393524-8

Removal Tool

For replacing the special contacts on connectors DIN 41612 M and SIEDECON.



ltem	Part No.		
Removal tool length 70 [2.76] length 200 [7.87]	2-1393524-4 2-1393524-6		
Spare part Ferrule	2-1393524-7		

1) Ferrule (spare part)